




### #PTO POSTERIORE PER CAMBIO MERCEDES



	<b>Output 1</b>	
<b>Torque (Nm)</b>	450	
<b>Int. ratio</b>	1,83	
<b>Number of axles</b>	2	

<b>Number of teeth</b>	12
<b>Module</b>	3
<b>Replace</b>	
<b>Replaced by</b>	

28/09/2018

#### Command type

- Electric    
  Hydraulic    
  Mechanic    
  Fixed engagement    
  Pneumatic    
  Vacuum system

